

Form IV
(See Rule 13)
ANNUAL REPORT

[To be submitted to the prescribed authority on or before 30th June every year for the period from January to December of the preceding year, by the occupier health care facility(HCF), or common bio-medical waste treatment facility (CBWTF)]

Return No : 3961592

Period : 2022

1. Particulars of the Occupier	
(i) Name of the authorized person (Occupier or operator of facility):	Suraj Shaw
(ii) Name of HCF or CBMWTF:	MEDICARE ENVIRONMENTAL MANAGEMENT PVT LTD
(iii) Address for Correspondence:	K-26, Phase-III, Industrial Growth Centre, Kalyani, Nandai
(iv) Address of Facility:	K-26, Phase - III, Industrial Growth Centre, Kalyani,
(v) Tel. No.:	9339213248
(vi) Fax. No.:	-
(vii) E-mail ID:	suraj.shaw@resustainability.com
(viii) URL of Website:	http://www.medicareenviro.com/
(ix) GPS coordinates of HCF of CBMWTF:	
(x) Ownership of HCF or CBMWTF:	Private
(xi) Status of Authorization under the BMW (Management and Handling) Rules:	Authorization No.: D0013712 Valid Upto: 31/05/2027
(xii) Status of Consents under Water Act and Air Act.:	Valid Upto: 31/05/2027
2. Type of Health Care Facility	
HCF/CBMWTF Type:	CBMWTF
(i) Number healthcare facilities covered by CBMWTF:	2260
(ii) No. of beds covered by CBMWTF:	31787
(iii) Installed treatment and disposal capacity of CBMWTF:	7600
(iv) Quantity of BMW treated or disposal by CBMWTF:	8292
3. Quantity of waste generated or disposed in Kg per annum (on monthly average basis)	Yellow Category: 2403775 Red Category: 292825 White Category: 73555 Blue Category: 50202 General Solid Waste: 0
4. Details of the Storage, Treatment, Transportation, Processing and Disposal Facility Details	
(i) Details of the on-site storage facility:	Size: 1000 Capacity: 10000 Provision of on-site storage:

(ii) Disposal Facility:	<table border="1"> <thead> <tr> <th>Type of Treatment Equipment</th> <th>Number of Units</th> <th>Capacity(Kg/day)</th> <th>Quantity Treated or Disposed(Kg/annum)</th> </tr> </thead> <tbody> <tr> <td>Incinerators</td> <td>1</td> <td>4800</td> <td>1752000</td> </tr> <tr> <td>Autoclaves</td> <td>1</td> <td>630</td> <td>689850</td> </tr> <tr> <td>Shredder</td> <td>1</td> <td>60</td> <td>350400</td> </tr> </tbody> </table>	Type of Treatment Equipment	Number of Units	Capacity(Kg/day)	Quantity Treated or Disposed(Kg/annum)	Incinerators	1	4800	1752000	Autoclaves	1	630	689850	Shredder	1	60	350400
Type of Treatment Equipment	Number of Units	Capacity(Kg/day)	Quantity Treated or Disposed(Kg/annum)														
Incinerators	1	4800	1752000														
Autoclaves	1	630	689850														
Shredder	1	60	350400														
(iii) Quantity of recyclable wastes sold to authorized recyclers after treatment in kg per annum:	416582.0																
(iv) No of vehicles used for collection and transportation of BMW:	21																
(v) Details of incineration, ash and ETP sludge generated, disposal during the treatment of wastes in Kg per annum	<table border="1"> <thead> <tr> <th>Type of waste</th> <th>Quantity Generated</th> <th>Where disposal</th> </tr> </thead> <tbody> <tr> <td>Ash</td> <td>162135</td> <td>WBWML</td> </tr> <tr> <td>ETP Sludge</td> <td>15000</td> <td>WBWML</td> </tr> </tbody> </table>	Type of waste	Quantity Generated	Where disposal	Ash	162135	WBWML	ETP Sludge	15000	WBWML							
Type of waste	Quantity Generated	Where disposal															
Ash	162135	WBWML															
ETP Sludge	15000	WBWML															
(vi) Name of the Common BMW Treatment Facility Operator through which wastes are disposed of:	WBWML																
5. Do you have BMW management committee:	no																
6. Training Conducted on BMW Details																	
(i) Number of training conducted on BMW Management:	101																
(ii) Number of personnel trained:	380																
(iii) Number of personnel trained at the time of induction:	28																
(iv) Number of personnel not undergone any training so far:	0																
(v) Whether standard manual for training is available:	yes																
(vi) Any other information:																	
7. Details of the accident occurred																	
(i) No. of accident occurred:	0																
(ii) Number of the persons affected:	0																
(iii) Remedial Action taken:	0																
(iv) Any Fatality occurred, details:	0																
8. Are you meeting the standards of air Pollution from the incinerator?. How many times in last year could not met the standards?:	yes, 1																
Details of Continuous online emission monitoring systems installed:	yes																
9. Liquid waste generated and treatment methods in place. How many times you have not met the standards in a year:	yes. 0																
10. Is the disinfection method or sterilization meeting the log for standards? How many times you have not met the standards in a year?:	yes. 0																
11. Any other relevant information:	Ventury, Scrubber, Mist Eliminator, Quencher,																

Name and Signature of the Head of the Institution

Date :20/07/2023

Place : *Nadia*